

Team America

4/19/2011

Leader: George Warner

Minutes: Bill Hazel

Minutes for Meeting #12

- MOSFET have failed once again
- Maybe back EMF is too much for these MOSFETs
- Add additional circuitry to prevent the back EMF from breaking MOSFET
- GSP is still underworks; the process to write strings to the LCD is still underway
- SD Card is still a work in progress, but we do have code from last year
- Cables still have to be made.
- Must measure lengths at the truck with Dr. Bauer