

Radio Flyers

EE 41440

11 April 2012

Minutes 04-11-12

Controls:

Meeting on Friday

Measuring thrust- Mechanicals might have a spring-loaded scale (john or Mr Brunell?)

ball park numbers online?

Use remote control, see PWM through logic analyzer, see current through clamp on current meter  
(not really needed)

Board

UART talking to terminal

Not tested I2C yet

Surveillance?

Send Schafer some options

Low pass filter algorithm (not Kalman)

Analog Code

Getting data out still a problem

PWM

Jay has that working

Battery Charger