

Power Rangers March 4, 2015

Meeting Leader: Evan Syers

Minutes: Meaghan Hannon

Attendance: M. Schafer, A. Lanre-Ladenegan, M. Hannon, S. Ritter, E. Syers

Minutes:

1. Converter Team PCB Board Comments
 - a. Remove loops from current sensor
 - b. No ground connection/overlap
 - c. Move connection to the side of board
 - d. Try to reduce size of board and add mounting holes
2. Microcontroller Team
 - a. Use unity gain buffer for microcontroller inputs
 - b. Microcontroller and Converter should be connected using Molex connectors for better safety
 - c. Work to finish Microcontroller PCB board before break