To: R.M. Schafer

From: Smart Windows

Date: April 18, 2010

Subject: Meeting Minutes

- 1. Ribbon cables and jumper wires are not a good option for making connections board to board.
 - a. Use male-female connectors
 - b. Stop office to get a see what the look like
- 2. Meeting @ 10:30pm 3/18/2010
 - a. Start preliminary board layout
 - b. Try using a ULP to generate SOIC