

Team America

2/22/2011

Leader: Bill Hazel

Minutes: Michael McSorley

Minutes for Meeting #5

- Parts for the auxiliary board have been ordered and they have arrived.
- The auxiliary board has shipped and should arrive by the end of the week.
- Temperature sensor discussion. It is possible to use a thermo couple cable attached to a converter IC.
- The SD card parts are expensive, but might have some in stock.
- GPS source code might have to be rewritten from last year
- It would be good to try and get NMEA signals and SPI interface working
- J-series not a good choice. Try the 4620 parts.
- Using kit boards for testing SPI interface
- SPI interface is a bus