

Team America

4/26/2011

Leader: Bill Hazel

Minutes: Michael McSorley

Minutes for Meeting #13

- Added diodes to the AUX board to address back EMF
- SD card still a work in progress
- Planning on going to the truck to measure cables
- Temperature sensor requires a thermocouple cable
- What type of thermocouple cable? J-type like last year?
- GSP is working, but still trying to output strings to the LCD screen