

## Meeting Minutes

Team Baja

11 February 2014

- Hall Effect Sensors acquired for engine and wheel speed
- Correct header files to use for Display Screen established
- Baud rate for GPS corrected
- Discussed using GPS to calculate vehicle speed
- Ascertained the acquisition of bread boards for prototyping with Hall Effect sensors