

Team America

3/8/2011

Leader: Billy Parker

Minutes: George Warner

Minutes for 3/8/2011

- Demonstrated turning generator on and off
- Turn generator on/off using ultracap voltages
- Write to SD card
- Vref for current sensor is an output voltage, not an input. Do not try to place a voltage on Vref.
- Started fire because of short to ground on oscilloscope.