

## Team Baja Agenda 2/25/14

- List of Subsystems
  - Engine & Wheel RPM Sensor - Patrick & Matt
    - Moved cart up into room 213
    - Found components in kit
    - Still no breadboard in kit or supply closet
    - Need a magnet for testing purposes
  - Display Screen – Stephen
    - Wrote a code for a simple display
  - GPS/SD Card Storage – Mike
    - Obtained 3D fix while testing outside of SR
    - Still unable to get GPS to register binary mode command
    - Questions about sending data to MDD
  
- Tasks for the coming week
  - Prototype magnet sensor on breadboard
  - Research spark plug RPM measuring technique
  - Expand on display code to increase complexity
  - Continue to attempt to get GPS into binary mode